

FIG. 1A






FIG. 1B

FIG. 1DFIG. 1C

TOP SECRET





FIG. 2A



4/9




FIG. 3

14716ROUS01U




FIG. 4




FIG. 5





FIG. 6

FIG. 7

Impact of a Mode Stripper [6umX80um] on a Butterfly MMI Split Ratio

